

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
52468609	075101
DATE 2-NOV-2019	

MOTOR CARRIER OPERATOR Fix trailer 3 derl decv	INSPECTOR'S NAME (PRINT OR TYPE)
ADDRESS Tomas Fernandez 3760	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.10. ☒ YES
CITY, STATE, ZIP CODE Juarez Chih. MX 32424	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	16RAA0629WB 075101 INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				10. TIRES
/			a. Service Brakes	/			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	/			a. Tires on any steering axle of a power unit.
/			b. Parking Brake System	/			b. Protection against shifting cargo.	/			b. All other tires.
/			c. Brake Drums or Rotors	/			c. Container securement devices on intermodal equipment.	/			11. WHEELS AND RIMS
/			d. Brake Hose	/				/			a. Lock or Side Ring
/			e. Brake Tubing	/				/			b. Wheels and Rims
/			f. Low Pressure Warning Device	/				/			c. Fasteners
/			g. Tractor Protection Valve	/				/			d. Welds
/			h. Air Compressor	/							12. WINDSHIELD GLAZING
/			i. Electric Brakes	/							Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
/			j. Hydraulic Brakes	/							13. WINDSHIELD WIPERS
/			k. Vacuum Systems	/							Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
			2. COUPLING DEVICES				7. STEERING MECHANISM				14. OTHER
/			a. Fifth Wheels	/			a. Steering Wheel Free Play	/			List any other condition(s) which may prevent safe operation of this vehicle.
/			b. Pintle Hooks	/			b. Steering Column	/			
/			c. Drawbar/Towbar Eye	/			c. Front Axle Beam and All Steering Components Other Than Steering Column	/			
/			d. Drawbar/Towbar Tongue	/			d. Steering Gear Box	/			
/			e. Safety Devices	/			e. Pitman Arm	/			
/			f. Saddle-Mounts	/			f. Power Steering	/			
			3. EXHAUST SYSTEM				g. Ball and Socket Joints	/			
/			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	/			h. Tie Rods and Drag Links	/			
/			b. Bus exhaust system leaking or discharging in violation of standard.	/			i. Nuts	/			
/			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	/			j. Steering System	/			
			4. FUEL SYSTEM				8. SUSPENSION				
/			a. Visible leak.	/			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.	/			
/			b. Fuel tank filler cap missing.	/			b. Spring Assembly	/			
/			c. Fuel tank securely attached.	/			c. Torque, Radius or Tracking Components	/			
			5. LIGHTING DEVICES				9. FRAME				
/			All lighting devices and reflectors required by Part 393 shall be operable.	/			a. Frame Members	/			
/				/			b. Tire and Wheel Clearance	/			
/				/			c. Adjustable Axle Assemblies (Sliding Subframes)	/			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK X NEEDS REPAIR NA IF ITEMS DO NOT APPLY REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

ORIGINAL